

### BACTERIOLOGICAL ANALYSIS - PUBLIC WATER SYSTEM

Laboratory ID #: 37501 County: DAVIDSON  
Water System ID #: 02-29-030  
Name of System: TOWN OF DENTON  
Sample Type:  5 (1 = Routine; 2 = Repeat; 3 = Replacement; 4 = Plan Approval; 5 = Other)  
Collected on: DATE: 05/15/18 TIME: 09:36 AM  
Location where collected: TOWN OF DENTON - TOWN HALL  
Location Type:  (1 = Entry Tap; 2 = General Tap; 3 = End Tap; 4 = Source/Intakes; 5 = Other)  
Location Code: SL1 Collected By: Rodney Darr

**FOR REPEAT SAMPLE:**

**FOR REPLACEMENT SAMPLE:**

Previous Positive Location Code: \_\_\_\_\_  
Positive Collection Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Proximity:  (1 = Same; 2 = Upstream; 3 = Downstream)

Original Sample Type:   
(1=Routine; 2=Repeat; 3=Plan Approval; 4=Other)  
Original Collection Date: \_\_\_\_\_  
Time: \_\_\_\_\_

Mail Results To:  
**WINSTON SALEM REGIONAL OFFICE PWSS**  
**450 WEST HANES MILL RD STE 300**  
**WINSTON SALEM, NC 27105**  
**Telephone No. 3367769800**  
**EIN #: 566000372X**      **COURIER #: 13-15-01**

Type of Supply:  
 Community       NTNC  
 Non-Community       Private  
Type of Treatment:  Chlorinated  
 Non-Chlorinated  
Free Chlorine Residual: 1.06 mg/l  
Total Chlorine Residual: \_\_\_\_\_

**RESULTS**

**INVALID CODES**

CONTAMINANT	METHOD	PRESENT	ABSENT	INVALID
Total Coliform	<u>9223B</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fecal/E. Coli	<u>9223B</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Heterotrophic P.C.	_____	_____	_____ /ml	

(number)

- 1) Confluent Growth/No Coliform Found
- 2) TNTC/No Coliform Found
- 3) Turbid Culture/No Coliform Found
- 4) Over 30 Hours Old
- 5) Improper Sample or Analysis

Repeat Samples Required

Replacement Samples Required

Date Analysis Begun: 05/16/18  
Date Analysis Completed: 05/17/18  
Laboratory Log #: \_\_\_\_\_

Time Analysis Begun: 09:35 AM  
Time Analysis Completed: 09:35 AM  
Certified By: Susan Beasley

COMMENTS: Sample Type: Routine (RT), Sample Point: Routine Original (RTOR), System  
Type: A, Water Source: SW, Disinfectant Used: Chlorine gas

